Cover Photograph: Date - February 10, 2002. Hazards associated with extinguishing the burning gob fire range from noxious gases and acidic steam to superheated conditions causing hydrogen gas explosions to occur without warning.